WILLIAMS COUNTY

Planning Unit 076: AML Printout #466: T153N, R100W, Section 4, E1/2

Additional Legal Location: Section 4, SE, NE

Name: Owner:

Williston View Mine No data

Category: Commercial/local

Type: Underground, drift (1938-1949) Underground, slope (1950)

Thickness

Overburden: Coal Seam: Mined: Source:

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

This mine is not listed as a new mine in 1938, and it may have been in operation prior to that time. The mine was operated and reported from 1938 through 1950. No listings were noted for this mine following 1950; it is not known if the mine ceased to be operated following 1950, if it was operated but not reported, or if it was operated and reported under some other name following that year.

Descriptive information pertaining to this mine is included in:

[source:year(pages)]

WCB Map:1939 (updated to 1942)

Notes:

The Black Diamond, Thompson, and Vizina coal mines also are located at this Planning Unit and AML location.

Sources (primary and secondary):

CMID: see table, next page, for appropriate years

WCB:1939 (updated to 1942)

Mine: Williston View Mine Planning Unit: 076
AML Number: 466

Year	Days Operated	Employees	Price Per Ton	Tons Produced	Tons Local Trade	Tons Shipped	Owner or Superintendent*
1938	208	no data	1.91+	1,200	1,200	none	Geo. Cox & Sons**
1939	220	4	1.40	2,450	2,450	none	Geo. E. Cox**
1940	203	4	1.60	2,211	2,211	none	Geo. E. Cox**
1941	200	3	1.40	1,857	1,857	none	Geo. Cox, Jr.**
1942	300	3	1.57	2,215	2,215	none	George Cox, Jr.**
1943	237	5	2.15	3,086	3,086	none	George Cox, Jr.**
1944	220	7	2.50	3,448	3,448	none	G.E. Cox & Son**
1945	268	6	2.50	2,933	2,933	none	G.E. Cox, Jr.**
1946	165	9	2.50	3 , 373	3 , 373	none	George Cox, Jr.**
1947	160	4	2.80	2,359	2,359	none	George Cox, Jr.**
1948	200	4	3.25	2,305	2,305	none	Jake Senti**
1949	170	3	3.25	3 , 150	3 , 150	none	Jacob Senti**
1950	150	3	3.25	2,238	2,230	none	Jacob Senti**

^{*}Unless otherwise indicated, name listed is that of owner.

^{**}Individual was superintendent of the mine; owner not listed.